



11-1-38















11-1-38







1. Diversion of brook.
2. Construction of concrete diaphragm.
3. Up-stream toe.
4. Puddle Clay pit.
5. Flood water entering tunnel, in Forebay before the bulk head was put in place, also showing bottom intake.
6. Concrete floor of Tailbay.
7. Shuttering for tunnel, looking down-stream from approximately, position of overflow, showing 22" delivery main.
8. Concrete tunnel at Forebay, showing bottom intake, incorporating bottom and cast iron joint ring. In distance, construction of diaphragm in up-stream toe.
9. Concrete forebay, showing erection of shuttering for beams.