





16.5.38



16-5-38.




16-5-38





16.5.38.





16.5.98.



16.5.38.





1. Forebay with first beam in position.
2. Tailbay showing compenssation weir and verticle cast iron pipe for level recorder.
3. Tailbay looking upstream.
4. Base of valve tower, showing tunnel.
5. Tunnel outlet into tailbay.
6. Down stream toe.
7. Concrete tunnel and foundations of overflow.
8. Conrete tunnel looking from tailbay to overflow.
9. Up-stream toe, showing concrete diaphram at point where old stream is filled in.