




Showing mass concrete construction. Wall thickened at deeper depths, and sloping dry stone toes.



Pillar supports, also showing beam to carry roof.



9" Sluice valves, before ball valves are added.



9"Sluice Valves, before ball  
valves are added.  
Mr. Simpson, Clerk of Works.



COREY WORKS SERVICE RESERVOIR

1940.



CORBY WORKS SERVICE RESERVOIR 1940  
General View.

Mr. Pownell, Junior Engineer.



Service Reservoir showing  
four, inlet valves and overflow.



Service Reservoir showing pillars.





Service Reservoir showing roof.  
1940.