





16.5.38



8-7-38









0-10-38



5-6-39





1. Northern end of Puddle Trench. 5.7.38.
2. Down Stream face of Dam nearing completion. Tail Bay in Foreground. 5.6.39.
3. Tail Bay in course of construction. 3.10.38.
4. Northern end of Puddle Trench, showing lights, so work could be continued at night. 29.7.38.
5. AS No. 4. 3.6.38.
6. Tail Bay completed. Nearest building, Loco shed, behind which is Engineer's shop, with cement shed and gravel elevator on left. Carpenter's shop in centre. Engineer's Offices in background with Watchman's hut. 8.1.40.
7. Looking North, pitching Up Stream Toe nearly complete. 5.7.38.
8. Puddle Trench, Northern end. 16.5.38.
9. Tail Bay, showing weir.